

Sports Surface Design & Management
 64 Porana Road
 Wairau Valley Auckland 0627
 New Zealand

Attention: Will Bowden

Project 14NZAK0036358
 Submission No. 24615
 Order Number 24615
 Despatched Date 16/05/2014
 Received Date 16/05/2014

Customer Sample ID	Remuera Golf Club Lake - Water	
Eurofins Sample No.	3753325	
Date Sampled	15/05/2014	
Test/Reference	Unit	
Heterotrophic Plate Count 30°C APHA, Current Edition; 9215 A,B Heterotrophic Plate Count 30°C	CFU/100mL	Pending
Total Coliforms count, Water (MF) APHA, Current Edition; 9222 B Total Coliforms	CFU/100mL	>150
Escherichia coli count, Water (MF) APHA, Current Edition; 9222 G Escherichia coli	CFU/100mL	>150
Sample Integrity		
Temperature on Arrival	13.5 °C	

Authorised By

Nikki Kantroo Senior Technician General Micro



Interim Report. Results may be subject to change. A final report will be issued once all testing is complete

* Indicates IANZ accreditation does not cover the performance of this service

- Indicates Not Requested

Eurofins NZ Laboratory Services Ltd shall not be liable for loss, cost, damages or expenses incurred by the client, or any other person or company, resulting from the use of any information or interpretation given in this report. In no case shall Eurofins NZ Laboratory Services Ltd be liable for consequential damages including, but not limited to, lost profits, damages for failure to meet deadlines and lost production arising from this report. This document shall not be reproduced except in full and relates only to the items tested. Unless indicated otherwise (**), the tests were performed on the samples as received.

The samples were not collected by Laboratory staff.